

## MAIN CAMPUS

1. Top rail and barbed wire damaged with a branch still on the fence.
2. Top rail disconnected from post.
3. Branch on barbed wire damaging barbed wire support brackets.
4. Barbed wire and support brackets damaged.
5. Overgrown vegetation.
6. Approximately 10" between the ground and the bottom of the fence.
7. Damaged support brackets and barbed wire
8. Vegetation overgrowing the fence.
9. Tree too close to the fence line.
10. Trees too close to the fence line.
11. Damaged support brackets and barbed wire.
12. Overgrown vegetation
13. Overgrown vegetation.
14. Damaged support bracket and barbed wire.
15. Damaged support bracket.
16. Tree on fence line.
17. Overgrown vegetation.
18. Damaged top rail, support brackets and barbed wire.
19. Approximately 8" between the ground and bottom of fence.
20. Damaged support brackets and barbed wire.
21. Damaged support brackets and barbed wire.
22. Damaged top rail, support brackets and barbed wire.

23. Tree on fence, damaged support brackets, barbed wire and top rail.
24. Damaged top rail and barbed wire.
25. Damaged top rail.
26. Damaged support bracket.
27. Damaged support bracket.
28. Damaged support bracket, barbed wire and top rail.
29. Damaged support brackets and top rail.
30. Damaged support brackets and top rail.
31. Damaged support brackets.

#### **EAST CAMPUS**

1. New temporary fence line and building.
2. Overgrown vegetation.
3. Support bracket missing, damaged top rail and barbed wire.

#### **AREA 100**

1. Overgrown vegetation.
2. Overgrown vegetation.
3. Overgrown vegetation.
4. Overgrown vegetation.
5. Overgrown vegetation, trees on fence, damaged top rail, support brackets, barbed wire.

### **AREA 200**

1. Support bracket damaged.
2. Tree on fence.
3. Damaged fence post, approximately 24" between fence and ground.
4. Tree on fence, damaged top rail and barbed wire.
5. Trees on fence, damaged top rails, support brackets and barbed wire.
6. Barbed wire damaged.
7. Trees on fence, damaged top rails, support brackets and barbed wire.
8. Damaged top rail, support brackets, fencing and barbed wire.
9. Tree on fence, damaged top rail, support bracket, and barbed wire.


### **AREA 300/400**

1. Damaged support bracket.
2. Damaged top rail, support bracket, barbed wire and fencing.
3. Damaged top rail, support bracket, barbed wire and fencing.
4. Tree on fence, damaged top rails, support brackets, fence post, barbed wire and fencing.
5. Tree on fence, damaged support brackets and top rail.
6. Damaged top rails, support brackets, barbed wire.
7. Damaged top rails, support brackets, top rail, barbed wire, fence posts and fencing.
8. Damaged top rails, support brackets, top rail, barbed wire, fence posts and fencing.

9. Tree on fence, damaged barbed wire.
10. Tree on fence, damaged top rail, support brackets, barbed wire and fencing.
11. Damaged top rails, support brackets, barbed wire and fencing.
12. Damaged top rails, support brackets, barbed wire, fencing and fence posts.
13. Damaged top rails and support brackets.
14. Damaged top rail, support bracket and barbed wire.
15. Damaged top rail, support bracket and barbed wire.
16. Tree on fence, damaged barbed wire.
17. Tree on fence, no damage.




1



2




3




4




5



6



7



8







9




10



11




12




13




14




15




16



17



18




19




20




21



22




23




24






25



26



27



28



29




30




31


EAST CAMPUS



1




2



3


AREA 100



1



2




3




4






5

AREA 200




1



2



3




4



5



6



7




8




9


AREA 300 AND 400




1



2




3




4







5




6



7



8




9



10




11




12




13




14



15



16



17

Garth P. Mahns

A handwritten signature in black ink, consisting of a stylized 'G' and 'M' followed by a horizontal line.

Security Analyst  
SecTek  
301-286-7090